







## 633LVH-AL40 Vapor Recovery Adaptor

### Replacement Parts

Rev. 0, January 2003



## 633LVH-1020 Vapor Recovery Adaptor



ITEM	PART NUMBER	DESCRIPTION	QTY.
1	E10000A	BODY	1
2	C02779M	SUPPORT BELL (DELTRIN)	1
3	H20750M	SEAT RING (VITON) <sup>1</sup>	1
4	H08841RA	STEM <sup>1</sup>	1
5	H09193M	COTTER PIN <sup>1</sup>	1
6	C51410A	POPPET <sup>1</sup>	1
7	H07365M	PIPE PLUG	1
8	H20007M	SPRING	1
9	H20010M	GASKET (BUNA)	2

ITEM	PART NUMBER	DESCRIPTION	QTY.
10	H20583M	SIGHT GLASS	2
11	H04135M	RETAINING PLATE	2
12	H52471M	HEX SCREW	6
13	101-0002	AIR INTERLOCK VALVE ASSY.	1

REPAIR KITS		
PART NUMBER	DESCRIPTION	QTY.
H20009	POPPET SUB-ASSEMBLY	N/A

1- Included in H20009